



TAM² SQUARED OPERATING, LLC



PETRA 11/28/2017 11:51:37 AM

Viola Prospect	
AMI	
Graben Block Faults Traced	
WELL SYMBOLS	
	Oil Well
	Gas Well
	Dry Hole
	Abandoned Location - Permit
	Dry Hole, With Show of Oil
	Dry Hole, With Show of Oil & Gas
	Dry Hole, With Show of Gas
	Plugged Gas Well
	Plugged Oil Well
By: LMP	
 0 10,677 FEET	
November 28, 2017	

LEASE BANK

214.460.9326 • TM2SQUARED@GMAIL.COM
 1920 BROKEN LANCE LN. • ROCKWALL, TX 75032



TM²SQUARED

AN ENERGY DEVELOPMENT COMPANY

TM2Squared Inc. LEASE BANK PROGRAM

Operator: TAM Squared Operating LLC
Direct: (469) 651-1490
Cellular: (214) 460-9326
Email: Tm2squared@gmail.com

Location: OKLAHOMA
Objective: Lease 640 Acres
Current Status: Funding

Investor Purchase of: \$300,000

Economics: Investment Cost: \$30,000 per Unit
Lease Bank will get 10% on Money Invested -When money raised on 1rst Well.
\$300,000+10%+ Override

Lease Bank : Gets .05 Override on all wells drilled on leased acreage

Oil & Gas Reserves: Oklahoma lease has recoverable reserves of 500,000 BO (plus)